## **Annexure D**

## **BUILDING SAFETY CERTIFICATE**

No154	Camp	NBC	24
-------	------	-----	----

Dated: 08:-04:-2024

...BUDAUN...... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the	6.0	6.0			_	
Block	G+3	G+2	_			

The building is owned/occupied by ZEALOT PUBLIC SCHOOL BUDAVIO (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.W.D. (Name of Department/ Govt.) on OG-04-2024 (date of inspection) in the presence of SMt. Rajni Devi, Manager of the School (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from O6-04-2024 for a period of 10 years years in accordance with rule and subject to compliance of the specific conditions as appended.

1. This Certificate is given on the basis of Map and Certificate provided by 2. Ar. Pallar Pratigogee, CA/2020/119762 and Stru. Engineer Vincet Kumar. 3. Singh AM-3090380.

1ssued on .08-04-2024 at Budaun by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

Name:

BRHISHER KUM

Designation सहायक अधियुना

Name & Address of Department Office: V. 0. - P

66 | Page